



Drill out eight holes with .25 dia drill bit.

ACV-F01-18  
Alternator rotor

Countersink four holes so 1/4-28X.625 screws are flush to .01 below surface with 82 degree countersink.